

VEHICLE INSPECTION REPORT

PE63NFR

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 06/11/2013

Year 2013

Mileage 1,195,692 Km
Warranted

Fuel Type DIESEL

GVW 7500kg

Colour RED

VIN XLRAE45FF0L432420

Body Style Box Van

Service history None

MOT Due 31/07/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Cracked
Replace

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Rusted
Over 5mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Poor Previous Repair
Rippled Up To 30%



7: Qtr Panel nsr
Cracked
Replace

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Dented
Over 30mm

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Pad osf
Soiled
Heavy

12: Carpets Front
Holed
Over 3mm



13: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		