

VEHICLE INSPECTION REPORT

ST62MHA

Ford Transit Connect T230 TDCi 90PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/01/2013

Year 2013

Mileage 85,535 Miles
Warranted

Fuel Type Diesel

GVW 2340kg

Colour WHITE

VIN WF0UXXTPUCS82727

Body Style Panel Van LWB

Service history Yes

Service documents Printout

MOT Due 30/01/2027

CAP Clean £1,200.00

CAP Average £950.00

CAP Below £625.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR, ROOF RACK.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Wing nsf
Dented
Over 30mm

4: Flasher Side Repeater os
Broken
Replace



5: Door osf
Dented
With Paint Damage

6: Sill os
Rusted
Over 5mm



7: Qtr Panel osr
Rusted
Over 5mm

8: Tailgate
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage

10: Sill ns
Rusted
Over 5mm



11: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK