

VEHICLE INSPECTION REPORT

PE63NNB

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/12/2013

Colour RED

Cab Type DAY CAB

Year 2013

VIN XLRAE45FF0L433294

Gearbox MANUAL

Mileage 862,610 Km Warranted

Body Style Box Van

Axle Combi 4x2

Fuel Type Diesel

MOT Due 30/09/2026

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4



OSO1

OSO2


OSO3

OSO4

Photos



Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bonnet
Cracked
Replace



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Other
N/A
N/A

6: Other
N/A
N/A



7: Other
N/A
N/A

8: Other
N/A
N/A



9: Bumper Rear
Rusted
Over 5mm

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Door osf
Chipped
Edge Chip



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Other
N/A
N/A



15: Other
N/A
N/A

16: Seat Base Cover nsf
Torn
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK